Reset
USB
Power
Power Switch
SD
Thermocouples
Extruder 1
Extruder 2
R
Y
R
Y
I/O
Buzzer
ICSP 2
ICSP 1
X-Stepper
Y-Stepper
Z-Stepper
A-Stepper (1)
B-Stepper (2)
X
Y
Z
A
B
Interface
Build Platform
Thermistor
I/O
UART
I2C
MakerBot
INDUSTRIES
RGB LEDs
X-Min
X-Max
Y-Min
Y-Max
Z-Min
Z-Max
Extruder 1
Heat (R) Fan
Safety
Cutoff
Extruder 2
Heat (L) Fan
Build Platform
Heat
Miscellaneous
Extra
Case
Fan